

Customer: Jacaranda West HOA #1 Inc. Account Number: 1489-7
Technician: Mike R Date: 9/7/2016 Time: 9:00am

SITE IDENTIFICATION NUMBERS

WATERWAY TREATMENT	2	3	6	7	8	14	15	16	20										
Algae	✓			✓															
Submersed Weeds	✓			✓															
Grasses and Brush	✓	→																	
Floating Weeds	✓				✓	✓	✓	✓	✓										
Mosquito Larvacide																			
Blue Dye																			
Restriction (# days)	∅	→																	
Inspection																			

- | | | | | | |
|--|---|--|--|--|--|
| CLARITY | FLOW | METHOD | CARP PROGRAM | WATER LEVEL | WATER TESTING |
| <input type="checkbox"/> <1' | <input type="checkbox"/> None | <input type="checkbox"/> Boat | <input type="checkbox"/> Carp Observed | <input type="checkbox"/> High | <input type="checkbox"/> Water Chemistry |
| <input checked="" type="checkbox"/> 1-2' | <input type="checkbox"/> Slight | <input type="checkbox"/> Truck | <input checked="" type="checkbox"/> Barriers Inspected | <input checked="" type="checkbox"/> Normal | <input type="checkbox"/> Bacteria Test |
| <input checked="" type="checkbox"/> 2-4' | <input checked="" type="checkbox"/> Visible | <input checked="" type="checkbox"/> Backpack | | <input type="checkbox"/> Low | Sample Site #: <u>n/a</u> |
| <input type="checkbox"/> >4' | | <input checked="" type="checkbox"/> ATV | | | |

*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

FISH/WILDLIFE OBSERVATIONS

- | | | | | |
|--|--|---|--|---|
| <input checked="" type="checkbox"/> Bass | <input checked="" type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input checked="" type="checkbox"/> Gambusia | <input checked="" type="checkbox"/> Turtles |
| <input checked="" type="checkbox"/> Egrets | <input checked="" type="checkbox"/> Herons | <input type="checkbox"/> Coots | <input checked="" type="checkbox"/> Gallinules | <input checked="" type="checkbox"/> Other Species |
| <input type="checkbox"/> Anhinga | <input type="checkbox"/> Cormorant | <input type="checkbox"/> Osprey | <input checked="" type="checkbox"/> Ibis | <u>Ducks</u> |
| <input type="checkbox"/> Woodstork | <input type="checkbox"/> Otter | <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snakes | |

NATIVE WETLAND HABITAT MAINTENANCE

- Beneficial Vegetation Noted:

- | | | | | |
|--|--|---|---------------------------------------|---|
| <input type="checkbox"/> Arrowhead | <input checked="" type="checkbox"/> Pickerelweed | <input checked="" type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush | <input type="checkbox"/> Blue Flag Iris |
| <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Gulf Spikerush | <input checked="" type="checkbox"/> Lily | <input type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> Duck Potato |
| <input checked="" type="checkbox"/> Bacopa | <input checked="" type="checkbox"/> Chara | <input type="checkbox"/> Naiad | | |

INVASIVE WEED CONTROL																			
Wicking																			
Spot Spraying																			
Physical Removal																			



Aquatic Systems, Inc.

LAKE & WETLAND MANAGEMENT SERVICES
2100 NW 33rd Street • Pompano Beach, FL 33069

EMAIL

CUSTOMER MANAGEMENT REPORT

1(800)432-4302

Customer: Jacaranda West HOA #1 Inc. Account Number: 1489-7

Technician: Jon S. Date: 9-13-16 Time: 8:15 AM

SITE IDENTIFICATION NUMBERS

WATERWAY TREATMENT	1	9																		
Algae	✓																			
Submersed Weeds	✓																			
Grasses and Brush	✓	✓																		
Floating Weeds		✓																		
Mosquito Larvacide																				
Blue Dye																				
Restriction (# days)	0	0																		
Inspection																				

CLARITY	FLOW	METHOD	CARP PROGRAM	WATER LEVEL	WATER TESTING
<input checked="" type="checkbox"/> <1'	<input checked="" type="checkbox"/> None	<input checked="" type="checkbox"/> Boat	<input checked="" type="checkbox"/> Carp Observed	<input checked="" type="checkbox"/> High	<input type="checkbox"/> Water Chemistry
<input checked="" type="checkbox"/> 1-2'	<input type="checkbox"/> Slight	<input type="checkbox"/> Truck	<input type="checkbox"/> Barriers Inspected	<input checked="" type="checkbox"/> Normal	<input type="checkbox"/> Bacteria Test
<input type="checkbox"/> 2-4'	<input type="checkbox"/> Visible	<input type="checkbox"/> Backpack		<input type="checkbox"/> Low	Sample Site #: _____
<input type="checkbox"/> >4'		<input type="checkbox"/> ATV			

*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

FISH/WILDLIFE OBSERVATIONS

- | | | | | |
|---|---|------------------------------------|--|---|
| <input checked="" type="checkbox"/> Bass | <input type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input checked="" type="checkbox"/> Gambusia | <input checked="" type="checkbox"/> Turtles |
| <input type="checkbox"/> Egrets | <input checked="" type="checkbox"/> Herons | <input type="checkbox"/> Coots | <input checked="" type="checkbox"/> Gallinules | <input type="checkbox"/> Other Species |
| <input checked="" type="checkbox"/> Anhinga | <input checked="" type="checkbox"/> Cormorant | <input type="checkbox"/> Osprey | <input type="checkbox"/> Ibis | _____ |
| <input type="checkbox"/> Woodstork | <input type="checkbox"/> Otter | <input type="checkbox"/> Alligator | <input type="checkbox"/> Snakes | _____ |

NATIVE WETLAND HABITAT MAINTENANCE

- Beneficial Vegetation Noted:

- | | | | | |
|------------------------------------|---|----------------------------------|---------------------------------------|---|
| <input type="checkbox"/> Arrowhead | <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush | <input type="checkbox"/> Blue Flag Iris |
| <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Gulf Spikerush | <input type="checkbox"/> Lily | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> _____ |
| <input type="checkbox"/> Bacopa | <input type="checkbox"/> Chara | <input type="checkbox"/> Naiad | | |

INVASIVE WEED CONTROL																				
Wicking																				
Spot Spraying																				
Physical Removal																				

Customer: Jacaranda West HOA #1 Inc Account Number: 1489-7
 Technician: Mike R Date: 9/27/2016 Time: _____

SITE IDENTIFICATION NUMBERS

WATERWAY TREATMENT	4	5	17	18															
Algae	✓																		
Submersed Weeds	✓																		
Grasses and Brush	✓		→																
Floating Weeds	✓		→																
Mosquito Larvacide																			
Blue Dye																			
Restriction (# days)	0		→																
Inspection																			

- | | | | | | |
|--|--|--|---|--|--|
| CLARITY | FLOW | METHOD | CARP PROGRAM | WATER LEVEL | WATER TESTING |
| <input type="checkbox"/> <1' | <input checked="" type="checkbox"/> None | <input type="checkbox"/> Boat | <input type="checkbox"/> Carp Observed | <input type="checkbox"/> High | <input type="checkbox"/> Water Chemistry |
| <input checked="" type="checkbox"/> 1-2' | <input type="checkbox"/> Slight | <input type="checkbox"/> Truck | <input type="checkbox"/> Barriers Inspected | <input checked="" type="checkbox"/> Normal | <input type="checkbox"/> Bacteria Test |
| <input checked="" type="checkbox"/> 2-4' | <input type="checkbox"/> Visible | <input checked="" type="checkbox"/> Backpack | | <input type="checkbox"/> Low | Sample Site #: <u>N/A</u> |
| <input type="checkbox"/> >4' | | <input type="checkbox"/> ATV | | | |

*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

FISH/WILDLIFE OBSERVATIONS

- | | | | | |
|--|--|---|--|---|
| <input checked="" type="checkbox"/> Bass | <input checked="" type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input checked="" type="checkbox"/> Gambusia | <input checked="" type="checkbox"/> Turtles |
| <input checked="" type="checkbox"/> Egrets | <input checked="" type="checkbox"/> Herons | <input type="checkbox"/> Coots | <input checked="" type="checkbox"/> Gallinules | <input type="checkbox"/> Other Species |
| <input type="checkbox"/> Anhinga | <input type="checkbox"/> Cormorant | <input checked="" type="checkbox"/> Osprey | <input checked="" type="checkbox"/> Ibis | <u>Ducks</u> |
| <input type="checkbox"/> Woodstork | <input type="checkbox"/> Otter | <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snakes | <u>Limkin</u> |

NATIVE WETLAND HABITAT MAINTENANCE

- Beneficial Vegetation Noted:

- | | | | | |
|--|--|---|---------------------------------------|--|
| <input type="checkbox"/> Arrowhead | <input checked="" type="checkbox"/> Pickerelweed | <input checked="" type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush | <input type="checkbox"/> Blue Flag Iris |
| <input type="checkbox"/> Cordgrass | <input checked="" type="checkbox"/> Gulf Spikerush | <input checked="" type="checkbox"/> Lily | <input type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> <u>Duck Potato</u> |
| <input checked="" type="checkbox"/> Bacopa | <input checked="" type="checkbox"/> Chara | <input type="checkbox"/> Naiad | | |

INVASIVE WEED CONTROL																			
Wicking																			
Spot Spraying																			
Physical Removal																			