

Customer: Jacaranda West HOA #1 Inc Account Number: 1489-7  
 Technician: Mike R Date: 10/13/2016 Time: 8:30am

**SITE IDENTIFICATION NUMBERS**

WATERWAY TREATMENT	1	9																		
Algae	✓																			
Submersed Weeds		✓																		
Grasses and Brush	✓	✓																		
Floating Weeds																				
Mosquito Larvacide																				
Blue Dye																				
Restriction (# days)	4	4																		
Inspection																				

- |  |  |  |   |  |  |
|--|--|--|---|--|--|
| <b>CLARITY</b>                           | <b>FLOW</b>                              | <b>METHOD</b>                            | <b>CARP PROGRAM</b>                         | <b>WATER LEVEL</b>                         | <b>WATER TESTING</b>                     |
| <input type="checkbox"/> <1'             | <input checked="" type="checkbox"/> None | <input checked="" type="checkbox"/> Boat | <input type="checkbox"/> Carp Observed      | <input type="checkbox"/> High              | <input type="checkbox"/> Water Chemistry |
| <input type="checkbox"/> 1-2'            | <input type="checkbox"/> Slight          | <input type="checkbox"/> Truck           | <input type="checkbox"/> Barriers/Inspected | <input checked="" type="checkbox"/> Normal | <input type="checkbox"/> Bacteria Test   |
| <input checked="" type="checkbox"/> 2-4' | <input type="checkbox"/> Visible         | <input type="checkbox"/> Backpack        |   | <input type="checkbox"/> Low               | Sample Site #: <u>N/A</u>                |
| <input type="checkbox"/> >4'             |  | <input type="checkbox"/> ATV             |   |  |  |

\*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

**FISH/WILDLIFE OBSERVATIONS**

- |   |   |   |                                     |   |
|---|---|---|-------------------------------------|---|
| <input type="checkbox"/> Bass               | <input type="checkbox"/> Bream                | <input type="checkbox"/> Catfish              | <input type="checkbox"/> Gambusia   | <input type="checkbox"/> Turtles                  |
| <input checked="" type="checkbox"/> Egrets  | <input type="checkbox"/> Herons               | <input type="checkbox"/> Coots                | <input type="checkbox"/> Gallinules | <input checked="" type="checkbox"/> Other Species |
| <input checked="" type="checkbox"/> Anhinga | <input checked="" type="checkbox"/> Cormorant | <input type="checkbox"/> Osprey               | <input type="checkbox"/> Ibis       | <u>Ducks</u>                                      |
| <input type="checkbox"/> Woodstork          | <input type="checkbox"/> Otter                | <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snakes     |   |

**NATIVE WETLAND HABITAT MAINTENANCE**

- Beneficial Vegetation Noted:

- |  |  |   |                                       |  |
|--|--|---|---------------------------------------|--|
| <input type="checkbox"/> Arrowhead         | <input checked="" type="checkbox"/> Pickerelweed   | <input checked="" type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush    | <input type="checkbox"/> Blue Flag Iris                |
| <input type="checkbox"/> Cordgrass         | <input checked="" type="checkbox"/> Gulf Spikerush | <input checked="" type="checkbox"/> Lily    | <input type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> <u>Duck Potato</u> |
| <input checked="" type="checkbox"/> Bacopa | <input checked="" type="checkbox"/> Chara          | <input type="checkbox"/> Naiad              |                                       |  |

INVASIVE WEED CONTROL																				
Wicking																				
Spot Spraying																				
Physical Removal																				

Customer: Caranda West HOA #1 Inc. Account Number: 1489-7  
 Technician: Mike R Date: 10/19/2016 Time: 9:00am

SITE IDENTIFICATION NUMBERS

WATERWAY TREATMENT	2	3	6	7	8	14	15	16	20											
Algae	✓					✓	✓	✓	✓											
Submersed Weeds	✓					✓	✓	✓	✓											
Grasses and Brush	✓	✓	✓	✓	✓	✓	✓	✓	✓											
Floating Weeds	✓	✓	✓	✓	✓	✓	✓	✓	✓											
Mosquito Larvaicide																				
Blue Dye																				
Restriction (# days)	0	→																		
Inspection																				

- |  |   |  |   |  |  |
|--|---|--|---|--|--|
| <b>CLARITY</b>                           | <b>FLOW</b>                                 | <b>METHOD</b>                                | <b>CARP PROGRAM</b>                         | <b>WATER LEVEL</b>                         | <b>WATER TESTING</b>                     |
| <input type="checkbox"/> <1'             | <input type="checkbox"/> None               | <input type="checkbox"/> Boat                | <input type="checkbox"/> Carp Observed      | <input type="checkbox"/> High              | <input type="checkbox"/> Water Chemistry |
| <input checked="" type="checkbox"/> 1-2' | <input type="checkbox"/> Slight             | <input type="checkbox"/> Truck               | <input type="checkbox"/> Barriers Inspected | <input checked="" type="checkbox"/> Normal | <input type="checkbox"/> Bacteria Test   |
| <input type="checkbox"/> 2-4'            | <input checked="" type="checkbox"/> Visible | <input checked="" type="checkbox"/> Backpack |   | <input type="checkbox"/> Low               | Sample Site #: <u>N/A</u>                |
| <input type="checkbox"/> >4'             |   | <input checked="" type="checkbox"/> ATV      |   |  |  |

\*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

FISH/WILDLIFE OBSERVATIONS

- |   |  |   |  |   |
|---|--|---|--|---|
| <input checked="" type="checkbox"/> Bass    | <input checked="" type="checkbox"/> Bream  | <input type="checkbox"/> Catfish              | <input checked="" type="checkbox"/> Gambusia   | <input checked="" type="checkbox"/> Turtles       |
| <input checked="" type="checkbox"/> Egrets  | <input checked="" type="checkbox"/> Herons | <input type="checkbox"/> Coots                | <input checked="" type="checkbox"/> Gallinules | <input checked="" type="checkbox"/> Other Species |
| <input checked="" type="checkbox"/> Anhinga | <input type="checkbox"/> Cormorant         | <input type="checkbox"/> Osprey               | <input checked="" type="checkbox"/> Ibis       | <u>Ducks</u>                                      |
| <input type="checkbox"/> Woodstork          | <input type="checkbox"/> Otter             | <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snakes                | <u>Cranes</u>                                     |

NATIVE WETLAND HABITAT MAINTENANCE

- Beneficial Vegetation Noted:

- |  |  |   |  |   |
|--|--|---|--|---|
| <input type="checkbox"/> Arrowhead         | <input checked="" type="checkbox"/> Pickerelweed   | <input checked="" type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush               | <input type="checkbox"/> Blue Flag Iris         |
| <input type="checkbox"/> Cordgrass         | <input checked="" type="checkbox"/> Gulf Spikerush | <input checked="" type="checkbox"/> Lily    | <input checked="" type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> Duck Potato |
| <input checked="" type="checkbox"/> Bacopa | <input type="checkbox"/> Chara                     | <input type="checkbox"/> Naiad              |  |   |

INVASIVE WEED CONTROL																				
Wicking																				
Spot Spraying																				
Physical Removal																				



# Aquatic Systems, Inc.

LAKE & WETLAND MANAGEMENT SERVICES

2100 NW 33rd Street • Pompano Beach, FL 33069

## CUSTOMER MANAGEMENT REPORT

1(800)432-4302

Customer: Sugarland West HOA #1 Inc

Account Number: 1489-7

Technician: Mike R

Date: 10/26/2016 Time: 9:00am

### SITE IDENTIFICATION NUMBERS

WATERWAY TREATMENT	4	5	17	18																
Algae			✓																	
Submersed Weeds			✓																	
Grasses and Brush	✓	✓	✓	✓																
Floating Weeds	✓	✓	✓	✓																
Mosquito Larvicide																				
Blue Dye																				
Restriction (# days)	∅	→																		
Inspection																				

- |  |  |  |  |  |   |
|--|--|--|--|--|---|
| <b>CLARITY</b>                           | <b>FLOW</b>                              | <b>METHOD</b>                                | <b>CARP PROGRAM</b>                                    | <b>WATER LEVEL</b>                         | <b>WATER TESTING</b>                                |
| <input type="checkbox"/> <1'             | <input checked="" type="checkbox"/> None | <input type="checkbox"/> Boat                | <input checked="" type="checkbox"/> Carp Observed      | <input type="checkbox"/> High              | <input checked="" type="checkbox"/> Water Chemistry |
| <input type="checkbox"/> 1-2'            | <input type="checkbox"/> Slight          | <input type="checkbox"/> Truck               | <input checked="" type="checkbox"/> Barriers Inspected | <input checked="" type="checkbox"/> Normal | <input type="checkbox"/> Bacteria Test              |
| <input checked="" type="checkbox"/> 2-4' | <input type="checkbox"/> Visible         | <input checked="" type="checkbox"/> Backpack |  | <input checked="" type="checkbox"/> Low    | Sample Site #: <u>N/A</u>                           |
| <input type="checkbox"/> >4'             |  | <input checked="" type="checkbox"/> ATV      |  |  |   |

\*NOTE: If a chemistry and/or bacteria test is required at this time you will receive a copy of the laboratory results under separate cover.

### FISH/WILDLIFE OBSERVATIONS

- |   |  |   |  |   |
|---|--|---|--|---|
| <input type="checkbox"/> Bass               | <input type="checkbox"/> Bream             | <input type="checkbox"/> Catfish              | <input checked="" type="checkbox"/> Gambusia   | <input checked="" type="checkbox"/> Turtles       |
| <input checked="" type="checkbox"/> Egrets  | <input checked="" type="checkbox"/> Herons | <input type="checkbox"/> Coots                | <input checked="" type="checkbox"/> Gallinules | <input checked="" type="checkbox"/> Other Species |
| <input checked="" type="checkbox"/> Anhinga | <input type="checkbox"/> Cormorant         | <input type="checkbox"/> Osprey               | <input checked="" type="checkbox"/> Ibis       | <u>Ducks</u>                                      |
| <input type="checkbox"/> Woodstork          | <input type="checkbox"/> Otter             | <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snakes                | <u>Limpkin</u>                                    |

### NATIVE WETLAND HABITAT MAINTENANCE

- Beneficial Vegetation Noted:

- |                                    |  |   |                                       |   |
|------------------------------------|--|---|---------------------------------------|---|
| <input type="checkbox"/> Arrowhead | <input checked="" type="checkbox"/> Pickerelweed   | <input checked="" type="checkbox"/> Bulrush | <input type="checkbox"/> Soft Rush    | <input type="checkbox"/> Blue Flag Iris         |
| <input type="checkbox"/> Cordgrass | <input checked="" type="checkbox"/> Gulf Spikerush | <input checked="" type="checkbox"/> Lily    | <input type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> Duck Potato |
| <input type="checkbox"/> Bacopa    | <input checked="" type="checkbox"/> Chara          | <input type="checkbox"/> Naiad              |                                       |   |

INVASIVE WEED CONTROL																				
Wicking																				
Spot Spraying																				
Physical Removal																				